



NOTES:

SEE ERECTION DRAWING P-081635 IF HIGH WIND GABLE TRIM CLIPS ARE REQUIRED

REV. DATE: 01/14/10	REV. NO. 00
KV393	

GABLE TRIM LEFT WITH MR-24 ROOF BUTLERIB II WALL PANEL W/O CLOSURE